



Fenway Park

Installation
2006

Location
Boston, MA

Materials
Strongcrete SW-81
Horizontal Repair
Mortar

Strongcote SC-111
Pedestrian Grade Coating

Strongfloor ET-1100
Aliphatic Coating

Contractor
McKinney Construction
Boston, MA

Standing water required this client to look for a product to re-pitch the bottom section of the newly constructed upper level at Fenway Park. SW-81 horizontal repair mortar was chosen as the overlay material to provide positive drainage. Upon completion of a variety of products and evaluations, both SC-111 and ET-1100 were used to coat the stairs in the new sections.



Architect/Engineer
Thompson & Litchner Company, Inc.
Cambridge, MA
& *Struever Bros. Eccles & Rouse, Inc.*
Boston, MA

swi Strongwall Industries, Inc.
Manufacturers of Concrete Restoration and Protection Systems
107 Chestnut Street
Ridgewood, NJ 07450
Tel: 201.445.4633