



Franklin Park

Installation
2003

Location
Boston, MA

Materials
Strongcrete SW-82
Vertical Repair Mortar

Rockbond RB-111
Exterior Finishing System

Contractor
PJ Spillane Company
Everett, MA

Franklin Park is a 150,000 sq. ft. public housing facility. SW-82 was specified for all vertical patching repairs. The RB-111 exterior finishing system was used to coat the entire facade.



Architect/Engineer
Thompson & Litchner Company, Inc
Cambridge, MA

swi Strongwall Industries, Inc.
Manufacturers of Concrete Restoration and Protection Systems
107 Chestnut Street
Ridgewood, NJ 07450
Tel: 201.445.4633