



Sinclair Community College


Installation
2006

The repairs on these columns at the community college garage were in excess of three inches in depth in some cases. The contractor chose a mortar from the specification; Strongwall's SW-88 deep vertical and overhead repair mortar. The workability and superior adhesion were key factors in his decision.

Location
Dayton, OH

Materials
Strongcrete SW-88 Vertical
and Overhead Repair Mortar

Contractor
DC Buyers



Architect/Engineer
LJB
Dayton, OH

swi Strongwall Industries, Inc.

107 Chestnut Street

Ridgewood, NJ 07450

Tel: 201.445.4633