



Francis Schervier Apartments

Installation
2003

Location
Bronx, NY

Materials
Rockbond RB-111
Exterior Finishing System
Resicolor #4

Contractor
Pinnacle Restoration
Glendale, NY

After completing spall repairs on this Bronx, NY apartment building, the contractor needed a coating to protect the concrete as well as adding pleasing aesthetics. The contractor chose two coats of RB-111 exterior finishing system and one coat of Resicolor #4 to enhance the facade of this 20,000 sq. ft. residential building.



swi Strongwall Industries, Inc.

Manufacturers of Concrete Restoration and Protection Systems

107 Chestnut Street
Ridgewood, NJ 07450

Tel: 201.445.4633