



## RTA BUS GARAGE

### Installation

2009

After reviewing their options, the Owners selected Strongcote SC-113 vehicular traffic coating to coat the 80,000 sq. ft. of this bus garage. After extensive tendon repairs were made to this post tensioned deck, as well as considerable concrete repairs, the entire surface was coated with three coats of SC-113.

### Location RTA

Dayton Regional  
Transit Authority  
4 South Main Street  
Dayton, OH 45402

### Materials

SW-81 Repair Mortar

Strongcote SC-113 Vehicular Grade

Traffic Coating



### Contractor

Advanced Restoration Contractors  
141 S Sherman Drive  
Indianapolis, IN 46201



**Strongwall Industries, Inc.** 107 Chestnut Street, Ridgewood, NJ 07450 **Website:** [www.strongwall.com](http://www.strongwall.com)  
**Office:** 201-445-4633 ♦ **Fax:** 201-447-2317 ♦ **Email:** [strongwall@strongwall.com](mailto:strongwall@strongwall.com)